Weathertzation Assistance

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: WO/90009MD2633/1

Work Order Type: Weatherization

Audit Name: 2633

CLIENT INFORMATION

Client ID: 90009MD2633

<u>AGENCY INFORMATION</u>

Agency: Metropolitan Development and Housing Agency

Agency Phone: (615) 252-8500

Address: 701 South Sixth Street Fax: (615) 252-8533

Nashville, TN 37206 *Email Address:*

Company Name & License Number:	
Contractor's Signature:	

COMMENT

AUDIT CONDUCTED1PM-3:00PM 3/21/2012 TIMOTHY KEY 615-330-4785

Client ID: 90009MD2633

CONTRACTOR IS RESPONSIBLE FOR VERIFIYING ALL MEASUREMENTS ALL WEATHERIZATION MEASURES AND REPAIRS MUST BE DONE FOLLOWING THE SOUTHEAST FIELD GUIDE

CERTITFIED FIRM/RENOVATOR REQUIRED IF HOME BUILT PRIOR TO 1978

Measur	e 1 Infilt	ration Redctn			Componen	ts		-	Inspected
Commer	2. D1 R 3. D2 RI 4. PATO 5. SEAL 7 BLOC 8. PATO HERE 9. SEAL 10. SEAL 11. BLO EXIST 12. SEA 13. SEA	ALL WINDOWS FROM EPLACE WS, TH, SEAL EPLACE WS, ADJUST HE GAZE HOLE @BR1 FLOW ELECTRICAL PANEL BOWNER OF CH 2X4 CEILING @ BR1 CK 5 HVAC VENTS @ FUS FLUMBING @ KITCHEN FOR THE WAROUND TUB PLUS FLUMBING @ KITCHEN FOR THE WAROUND TUB PLUS FOR THE WARD TO WA	EXTERION ARDWARDOR BOX @ CR. D1 CLOSET WALLS @ TCHEN CAFLOOR WALLS & CAFLOOR	OR FRARE FOR ACKS INSTA CEILIABINET	R TIGHT FIT WALL SLL NEW AT NG 40 LN FITS	TIC ACC			
					Estimated	<u> </u>		Actual	
# Materia	/ Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Miscell	aneous Su	Infiltration Reduction	Each	1					
Other Det	ail								
				Measur	e Sub Total:			Sub Total:	
Field No	tes:								

_	Measure 2 Attic		- 4.1		Componen	ts A1		ı	nspected
C	comment 0 EXIST	. ADD 12 INCH 12 TOT	AL INCH	ES BI	JILD DAM <i>Estimated</i>	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Cellulose, Blown - R-38	SqFt	806					
2	Labor	Attic Insulation - Cellulose, Blown - R-38	SqFt	806					
C	Other Detail						1		
L									
L				Measur	e Sub Total:] []	Sub Total:	
	Field Notes:								
		I Tank Insulation			Componen	ts			Inspected
	Measure 3 DWH				Componen Estimated			I Actual	Inspected
C			Units	Qty	-		Qty		Inspected
<i>C</i>	Comment ELECTR Material / Labor	RIC WRAP TANK	<i>Units</i> Each		Estimated		Qty	Actual	
C #	Comment ELECTR	CIC WRAP TANK Description / Comment		Qty	Estimated		Qty	Actual	
C # 1	Comment ELECTR Material / Labor Hot Water Equipm	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	
C # 1	Comment ELECTR Material / Labor Hot Water Equipm Labor	Description / Comment DHW Tank Insulation	Each	Qty 1	Estimated		Qty	Actual	Total
C # 1	Comment ELECTR Material / Labor Hot Water Equipm Labor	Description / Comment DHW Tank Insulation	Each Each	Qty 1 1	Estimated			Actual	

Measure 4 D	WH Pipe Insulation			Componen	ts			Inspected
Comment ELEC	TRIC WRAP HOT PLUS C	OLD LINE	S. LO	CATED UNI	DER HON	ΛE.		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail]		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
Measure 5 Fl	oor Ins. R-19			Componen	ts F1		ı	Inspected
	JN JUIST							
	JH JUIST			Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Estimated Unit Cost	Total	Qty	Actual Unit Cost	Total
		<i>Units</i> SqFt	Qty 806		 -	Qty		Total
# Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation -				 -	Qty		Total
1 Insulation	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	806		 -	Qty		Total
1 Insulation	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt	806		 -	Qty		Total
1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt	806		 -	Qty		Total
1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt SqFt	806	Unit Cost	 -		Unit Cost	Total
1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt SqFt	806		 -			Total
1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt SqFt	806	Unit Cost	 -		Unit Cost	Total
1 Insulation 2 Labor Other Detail	Description / Comment Floor Insulation - Fiberglass Faced Batt - R-19 Floor Insulation - Fiberglass Faced Batt -	SqFt SqFt	806	Unit Cost	 -		Unit Cost	Total

Inspected Components HS1,AC1 Measure 6 Install/Replace Heatpump Comment SPACE HEATER EXISTING.. INSTALL NEW COMBO UNIT @ WD6 IN FRONT OF HOME **Estimated** Actual # Material / Labor **Description / Comment Units Unit Cost** Total Qty **Unit Cost** Total Qty Heating Equipmen Heatpump - 18 kBtu/h Each 1 Existing, Consult Manual J Data 2 Labor Heatpump - 18 kBtu/h Each 1 Existing, Consult Manual J Data Other Detail Sub Total: Measure Sub Total: Field Notes: Inspected **Measure 7** Wall Insulation Components WL1,WL2,WL3,WL4, WL5,WL6 **Comment** DENSE PACK FROM EXTERIOR. WOOD EXTERIOR. **Estimated** Actual # Material / Labor **Unit Cost** Total Qty **Unit Cost** Total **Description / Comment Units** Qty Insulation Wall Insulation -SqFt 714.3 Cellulose, Blown - 2x4 Filled 2 Labor Wall Insulation -SqFt 714.3 Cellulose, Blown - 2x4 Filled Other Detail Sub Total: Measure Sub Total: Field Notes:

_		Monitor is Needed			Componen	ts		1	Inspected
C	comment				Estimated	,		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
	Health and Safety		Each	1		70147	 - 		7000
•	rioditir and carety	oo momoi	_00	·					
2	Labor	Labor	Each	1					
C	Other Detail								
				Measur	e Sub Total:			Sub Total:	
	Field Notes:								
	Measure 9 Smo Comment	ke Detector is Needed			Componen				Inspected
C	Comment				Estimated	1		Actual	
<i>C</i>	Comment Material / Labor	Description / Comment	Units	Qty	•		Qty		Inspected Total
<i>C</i>	Comment	Description / Comment	<i>Units</i> Each		Estimated	1	Qty	Actual	
C #	Comment Material / Labor	Description / Comment		Qty	Estimated	1	Qty	Actual	
C # 1	Comment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Comment Material / Labor Health and Safety	Description / Comment Smoke detector	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Comment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	Qty 1	Estimated	1	Qty	Actual	
C # 1	Comment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	Qty 1 1	Estimated	1		Actual	
C # 1	Comment Material / Labor Health and Safety Labor	Description / Comment Smoke detector	Each	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	
C # 1	Material / Labor Health and Safety Labor Other Detail	Description / Comment Smoke detector	Each	Qty 1 1	Estimated Unit Cost	1		Actual Unit Cost	

Measure 10 Vapor Barrier Needed (Basement/Crawlspace) 1106 SQ/FT					Components					
C	omment OVERLA	AP 12" AND RUN UP WA	ALLS AND	PIER	12"					
				Estimated						
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Health and Safety	Basement / crawlspace vapor barrier	SqFt	1						
2	Labor	Labor	SqFt	1						
C	Other Detail									
				Measur	e Sub Total:			Sub Total:		
	Field Notes:									
			Work Oi	rder Gra	and Total:		Gran	d Total:		